

Assistant Municipal Commissioner
Hadapsar – Mundhava Office
Pune Municipal Corporation.

Out ward No:- 909602


Date:- 01/01/2024

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

Ref.No. :- Assistant Municipal Commissioner Office, Hadapsar – Mundhava Inward
No. 13776 Date. 14/12/2023.

It is certificate that an inspection team headed by Mr.Shelar Navnath Maruti.Sanitary Inspector, Assistant Municipal Commissioner Office, Hadapsar – Mundhava, Pune Municipal Corporation From Health Department (Sanetartation) inspected The Cygnet Public School, S.No.58, HAndewadi Road, Hadapsar, Pune 412308. On 04 January 2024 and found that Cygnet Public School, S.No.58, HAndewadi Road, Hadapsar, Pune 412308. Has Safe Drinking Water Facilities for the students and member of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T.Govt.

The Above Valid For a Period of One Year.


(Navnath Shelar)

Sanitary Inspector

Hadapsar-Mundhwa ward office

Pune Muncipal corporation


(Sachin Laddkat)

Senior Sanitary Inspector
Hadapsar-Mundhwa ward office

Pune Muncipal corporation

To,
Cygnet Public School
S.No.58, HAndewadi Road,
Hadapsar, Pune 412308.